COPE

00684.003286 <u>PATENT</u>

PE CLE WOLLD TO THE TRADE TRADE THE TRADE THE

### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

Examiner: R. Beatty

HIROOMI MATSUZAKI

Group Art Unit: 2852

Appln. No.: 09/988,342

Patent No.: 6,792,229 B2

Filed: November 19, 2001

Issued: September 14, 2004

For: PROCESS CARTRIDGE,

ELECTROPHOTOGRAPHIC IMAGE

FORMING APPARATUS AND

CARTRIDGE MOUNTING METHOD

Examiner: R. Beatty

Issued: September 12, 2052

November 16, 2004

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450 Certificate
NOV 2 2 2004

Attention: CERTIFICATE OF CORRECTION BRANCH

of Correction

# REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

11/17/2004 NNGUYEN2 00000195 6792229

01 FC:1811 100.00 OP

Accompanying this letter is a check for \$100.00 to cover the statutory fee for issuing a Certificate of Correction to correct errors of the patentee. Any deficiency should be charged, or any overpayment credited, to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for this purpose.

Patentee's attorney, Gary M. Jacobs, may be reached by telephone in our Washington, D.C. office at (202) 530-1010 or by facsimile at (202) 530-1055. All correspondence should be directed to our address given below.

Respectfully submitted,

Jack S. Cubert

Attorney for Patentee Registration No. 24,245

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2200

JSC/llp

DC\_MAIN 184029v1

### **CERTIFICATE OF CORRECTION**

PATENT NO. :

6,792,229 B2

DATED

September 14, 2004

INVENTOR(S) :

Hiroomi Matsuzaki

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### ON THE COVER PAGE

In Item (56), References Cited, Foreign Patent Documents, "06130742 5/1994" should read --6-130742 5/1994--.

In Item (57), Abstract, line 5, "an" should read --a--.

In Item (57), Abstract, line 12, "portion" should read --portion of--.

### COLUMN 9

Line 31, "above described" should read --above-described--.

### COLUMN 10

Line 45, "above described" should read -- above-described--.

### COLUMN 11

Line 10, "21 a" should read --21a--.

Line 28, "21 a" should read --21a--.

Line 34, "21 a" should read --21a--.

#### COLUMN 12

Line 14, "above described" should read --above-described--.

Line 21, "maybe" should read --may be--, and "above described" should read --above-described--.

Line 23, "above" should read -- above- --.

Line 42, "above described" should read -- above-described--.

### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) GMJ/Ilp DC\_MAIN 184035

PATENT NO. 6,792,229 B2

No. of add'l. copies @ 30¢ per page

354

### **CERTIFICATE OF CORRECTION**

PATENT NO. :

6,792,229 B2

**DATED** 

September 14, 2004

INVENTOR(S) :

Hiroomi Matsuzaki

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### COLUMN 13

Line 66, "above described" should read --above-described--.

### COLUMN 14

Line 2, "above described" should read --above-described--.

Line 28, "above described" should read --above-described--.

Line 65, "hot melting" should read --hot-melting--.

### COLUMN 15

Line 36, "bole" should read --hole--.

#### COLUMN 17

Line 20, "above described" should read -- above-described--.

### **COLUMN 18**

Line 67, "above described" should read -- above-described--.

### **COLUMN 19**

Line 55, "nondriven" should read --non-driven--.

#### COLUMN 20

Line 54, "above described" should read --above-described--.

### **MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

(212) 210-2200 - Tacsi

Form PTO 1050 (Rev. 3-82)
(Form#30) GMJ/lip DC\_MAIN 184035

PATENT NO. 6,792,229 B2

No. of add'l. copies @ 30¢ per page



NOV 2 9 2004

### **CERTIFICATE OF CORRECTION**

PATENT NO. :

6,792,229 B2

DATED

September 14, 2004

INVENTOR(S) :

Hiroomi Matsuzaki

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### **COLUMN 21**

Line 58, "above described" should read -- above-described ---.

### **COLUMN 24**

Line 41, "an" should read --a--.

#### **COLUMN 27**

Line 14, "26." should read --26,--.

### **COLUMN 29**

Line 14, "above" should read -- above- --.

Line 51, "above" should read --above- --.

Line 66, "above described" should read -- above-described --.

### COLUMN 30

Line 64, "above described" should read --above-described--.

### **COLUMN 31**

Line 27, "72a" should read --72a.--.

#### COLUMN 32

Line 11, "surround" should read --surrounds--.

Line 58, "above described" should read --above-described--.

### **MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) GMJ/Ib DC\_MAIN 184035

PATENT NO. <u>6,792,229 B2</u>

No. of add'l. copies @ 30¢ per page

NOV 2 9 2004

### **CERTIFICATE OF CORRECTION**

PATENT NO. :

6,792,229 B2

DATED

September 14, 2004

INVENTOR(S) :

Hiroomi Matsuzaki

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### **COLUMN 33**

Line 15, "comer" should read --corner--. Line 18, "above" should read --above- --.

### COLUMN 37

Line 29, "above" should read --above- --. Line 36, "comer" should read --corner--.

#### COLUMN 38

Line 6, "15 a" should read --15a--.

### COLUMN 50

Line 33, "recess said" should read --recess and said--.

### COLUMN 54

Line 9, "apart" should read --a part--.

### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)
(Form#30) GMI/IIp DC\_MAIN 184035

PATENT NO. <u>6,792,229 B2</u>

No. of add'l. copies @ 30¢ per page

 $\Rightarrow$ 

NOV 2 9 2004

E 98684.003286 PATENT

### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

)	
:	Examiner: R. Beatty
)	
:	Group Art Unit: 2852
)	-
:	Patent No.: 6,792,229 B2
)	
:	Issued: September 14, 2004
)	- -
:	November 16, 2004
)	
:	
	) : ) : ) : )

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Attention: CERTIFICATE OF CORRECTION BRANCH

## REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for issuing a Certificate of Correction to correct errors of the patentee. Any deficiency should be charged, or any overpayment credited, to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for this purpose.

Patentee's attorney, Gary M. Jacobs, may be reached by telephone in our Washington, D.C. office at (202) 530-1010 or by facsimile at (202) 530-1055. All correspondence should be directed to our address given below.

Respectfully submitted,

Jack S. Cubert

Attorney for Patentee Registration No. 24,245

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2200

JSC/llp

DC\_MAIN 184029v1

### **CERTIFICATE OF CORRECTION**

PATENT NO. :

6,792,229 B2

DATED

September 14, 2004

INVENTOR(S) :

Hiroomi Matsuzaki

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### ON THE COVER PAGE

In Item (56), References Cited, Foreign Patent Documents, "06130742 5/1994" should read --6-130742 5/1994--.

In Item (57), Abstract, line 5, "an" should read --a--.

In Item (57), Abstract, line 12, "portion" should read --portion of--.

### COLUMN 9

Line 31, "above described" should read --above-described--.

### COLUMN 10

Line 45, "above described" should read -- above-described--.

### **COLUMN 11**

Line 10, "21 a" should read --21a--.

Line 28, "21 a" should read --21a--.

Line 34, "21 a" should read --21a--.

### COLUMN 12

Line 14, "above described" should read --above-described--.

Line 21, "maybe" should read --may be--, and "above described" should read --above-described--.

Line 23, "above" should read --above- --.

Line 42, "above described" should read --above-described--.

### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30) GMJ/lip DC\_MAIN 184035 PATENT NO. 6,792,229 B2

No. of add'l. copies @ 30¢ per page

 $\Rightarrow$ 

### CERTIFICATE OF CORRECTION

PATENT NO. :

6,792,229 B2

DATED

September 14, 2004

INVENTOR(S) :

Hiroomi Matsuzaki

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### **COLUMN 13**

Line 66, "above described" should read --above-described--.

### COLUMN 14

Line 2, "above described" should read --above-described--.

Line 28, "above described" should read --above-described--.

Line 65, "hot melting" should read --hot-melting--.

### **COLUMN 15**

Line 36, "bole" should read --hole--.

### COLUMN 17

Line 20, "above described" should read --above-described--.

### COLUMN 18

Line 67, "above described" should read --above-described--.

### COLUMN 19

Line 55, "nondriven" should read --non-driven--.

### COLUMN 20

Line 54, "above described" should read --above-described--.

### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

PATENT NO. 6,792,229 B2

Form PTO 1050 (Rev. 3-82)

(Form#30) GMJ/lip DC\_MAIN 184035

### **CERTIFICATE OF CORRECTION**

PATENT NO. :

6,792,229 B2

**DATED** 

September 14, 2004

INVENTOR(S) :

Hiroomi Matsuzaki

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### **COLUMN 21**

Line 58, "above described" should read --above-described--.

### **COLUMN 24**

Line 41, "an" should read --a--.

### **COLUMN 27**

Line 14, "26." should read --26,--.

### **COLUMN 29**

Line 14, "above" should read --above- --.

Line 51, "above" should read --above- --.

Line 66, "above described" should read --above-described--.

### COLUMN 30

Line 64, "above described" should read --above-described--.

#### COLUMN 31

Line 27, "72a" should read --72a.--.

### **COLUMN 32**

Line 11, "surround" should read --surrounds--.

Line 58, "above described" should read -- above-described ---.

#### **MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)
(Form#30) GMJ/Ilp DC\_MAIN 184035

PATENT NO. 6,792,229 B2

No. of add'l. copies @ 30¢ per page

 $\Rightarrow$  \_\_\_\_

### CERTIFICATE OF CORRECTION

PATENT NO. :

6,792,229 B2

**DATED** 

September 14, 2004

INVENTOR(S) :

Hiroomi Matsuzaki

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### **COLUMN 33**

Line 15, "comer" should read --corner--. Line 18, "above" should read -- above- --.

### **COLUMN 37**

Line 29, "above" should read --above- --. Line 36, "comer" should read --corner--.

### **COLUMN 38**

Line 6, "15 a" should read --15a--.

### COLUMN 50

Line 33, "recess said" should read --recess and said--.

### **COLUMN 54**

Line 9, "apart" should read --a part--.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone

Form PTO 1050 (Rev. 3-82) (Form#30) GMI/Ilp DC\_MAIN 184035

(212) 218-2200 - Facsimile

PATENT NO. 6,792,229 B2

No. of add'l. copies @ 30¢ per page